

Inspection Photos  
Location: Frazee No. 2-6  
Location ID: 324831  
API # 05-061-06365



Photo 1 – Well placard at tank battery

Photo 2 – Tank Battery

**Inspection Photos**  
**Location: Frazee No. 2-6**  
**Location ID: 324831**  
**API # 05-061-06365**



**Photo 3 – Stained soils**

**Photo 4 – Fencing not maintained**

Inspection Photos  
Location: Frazee No. 2-6  
Location ID: 324831  
API # 05-061-06365



Photo 5 – Fencing not maintained

Photo 6 – Placard at wellhead

**Inspection Photos**  
**Location: Frazee No. 2-6**  
**Location ID: 324831**  
**API # 05-061-06365**



**Photo 7 – Impacted soils**