

# Inspection Photos

API: 017-07614

Operator: MULL DRILLING COMPANY

Inspection Date: 6/4/2025

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast toward the location. The vegetation has not established at the location. Soils appear to be impacted.





## Inspection Photos



**Photo 2.** Facing west at the location. This area is approx. 120'x120' in size.





## Inspection Photos



**Photo 3.** Facing south at the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 4.** Facing north toward the surrounding undisturbed reference area.

