

# Final Reclamation and Stormwater Inspection

June 4, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 320334

Well Name: EDSTROM 24-8 #1

Inspection Document #: 718600643

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: EDSTROM 24-8 #1  
Location ID: 320334



**Photo 1.** Looking south across the wellbore. Some desirable vegetation is present around the wellbore and appears to be progressing towards 80% of the reference area.



**Photo 2.** Looking east from the wellbore. A monitoring well is present approximately 50 ft east of the wellbore (red circle) and does not appear to be associated with the previous remediation project.

Inspection Photos  
Location Name: EDSTROM 24-8 #1  
Location ID: 320334



**Photo 3.** Looking north from the wellbore. This PA location is adjacent to active location ID 427862.



**Photo 4.** Looking south across the former tank battery location. Vegetation is primarily undesirable weeds such as Kochia with very little desirable vegetation establishment. . A black silt fence runs through the former tank battery area.

Inspection Photos  
Location Name: EDSTROM 24-8 #1  
Location ID: 320334



**Photo 5.** Looking south across the tank battery. See photo 5 comments.



**Photo 6.** Near the silt fence on the tank battery, a marker labeled “const limit” is present.

Inspection Photos  
Location Name: EDSTROM 24-8 #1  
Location ID: 320334



**Photo 7.** Reference vegetation to the west of the location.

Inspection Photos  
Location Name: EDSTROM 24-8 #1  
Location ID: 320334



**Photo 8.** Google earth aerial imagery taken 03/2025. Silt fence with marker labeled “const limit” is present on former tank battery (red circle).

