

Inspection Photos
Location: MPU Press Maint and Inject Facility
Location ID: 255968
Spill ID # 489244 and 489245



Photo 1 – Placard at facility

Photo 2 – Excavation area 1

Inspection Photos
Location: MPU Press Maint and Inject Facility
Location ID: 255968
Spill ID # 489244 and 489245



Photo 3 – Excavation area near equipment.

Photo 4 – Spoil pile

Inspection Photos
Location: MPU Press Maint and Inject Facility
Location ID: 255968
Spill ID # 489244 and 489245



Photo 5 – Excavation area 2 at tank