

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC N PARACHUTE WF09B-25I25A596 Pad

Location #: 335651



Photo # 6278 From entrance to location




Photo # 6279 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC N PARACHUTE WF09B-25I25A596 Pad

Location #: 335651



Photo # 6280 Location



Photo # 6281 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC N PARACHUTE WF09B-25I25A596 Pad

Location #: 335651



Photo # 6282 Location




Photo # 6283 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC N PARACHUTE WF09B-25I25A596 Pad

Location #: 335651



Photo # 6284 Location



Photo # 6285 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC N PARACHUTE WF09B-25I25A596 Pad

Location #: 335651



Photo # 6286 Location



Photo # 6287 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC N PARACHUTE WF09B-25I25A596 Pad

Location #: 335651



Jun 4, 2025 at 2:09:51 PM

Photo # 6288 Location



Jun 4, 2025 at 2:03:48 PM

Photo # 6289 Open ended load line

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC N PARACHUTE WF09B-25I25A596 Pad

Location #: 335651



Photo # 6290 Debris



Photo # 6291 Debris