Remediation
Soil & Groundwater Sampling Fieldsheet

* * * Facility Information * * *

O&G Site Name	Turkey Springs 1N-14HZ Wellhead	**Client**	Oxy	REM Project #	40079
Weather	85°F, Sunny	**Surface Flow Direction**	East		
API/TB#	05-123-36814	**Liner present?**	N/A	**Site Coordinates**	40.130200, -104.738104

Directions to Well: WCR 20 & WCR 37,W 1 mile, S 300',W 2/10 into

* * * Sampling Information * * *

Sample Date 5/13/2025

Sampler(s) CH

Sample ID	Time	Date	Lab?	PID (ppm)	Location Description	Staining/ Odor	Color/ Lithology	
WH-B01@6'	13:45	5/13/2025	Yes	0.3	Base of WH	N	BRN	LOAMY SAND
WH-Riser@4'	13:50	5/13/2025	Yes	0.9	FL Riser at WH	N	BRN	LOAMY SAND
WH-N01@3'	13:55	5/13/2025	No	2.6	N Side Wall of WH Excavation	N	BRN	LOAMY SAND
WH-E01@3'	13:57	5/13/2025	No	2.3	E Side Wall of WH Excavation	N	BRN	LOAMY SAND
WH-S01@3'	14:00	5/13/2025	No	0.2	S Side Wall of WH Excavation	N	BRN	LOAMY SAND
WH-W01@3'	14:02	5/13/2025	No	0.0	W Side Wall of WH Excavation	N	BRN	LOAMY SAND
WHS-N01@3"	14:04	5/13/2025	No	0.5	N Surface of WH Excavation	N	BRN	LOAMY SAND
WHS-E01@3"	14:06	5/13/2025	No	6.0	E Surface of WH Excavation	N	BRN	LOAMY SAND
WHS-S01@3"	14:08	5/13/2025	No	5.6	S Surface of WH Excavation	N	BRN	LOAMY SAND
WHS-W01@3"	14:10	5/13/2025	No	5.3	W Surface of WH Excavation	N	BRN	LOAMY SAND

Decon Methods: Alconox & DI Water

Depth GW observed: None

GW Sampling

Sample ID	Date	Time	Odor?	Sheen?	Sample ID	Date	Time	Odor?	Sheen?

Site Comments: Unable to collect BKGs on 5/13/25. Need locates to extend past 225' exclusionary zone.

Sampling Photographic Log

Turkey Springs 1N-14HZ Wellhead

Description:

WH-B01@6'

WH-N01@3'

WH-E01@3'