

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/2-34 Pad

Location ID: 312496

Date: 06/4/2025



Photo # 7662 Entrance to location



Photo # 7678 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/2-34 Pad

Location ID: 312496

Date: 06/4/2025



Photo # 7664 Location/wellhead sign becoming illegible



Photo # 7667 Location



Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/2-34 Pad

Location ID: 312496

Date: 06/4/2025



Photo # 7676 Location



Photo # 7691 SE corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/2-34 Pad

Location ID: 312496

Date: 06/4/2025



Photo # 7692 NE corner of location



Photo # 7693 NW corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/2-34 Pad

Location ID: 312496

Date: 06/4/2025



Photo # 7694 SW corner of location



Photo # 7674 Staining

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/2-34 Pad

Location ID: 312496

Date: 06/4/2025



Photo # 7680 Staining on side of tank



Photo # 7685 Wildlife hazard

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/2-34 Pad

Location ID: 312496

Date: 06/4/2025



Photo # 7688 Wildlife hazard



Photo # 7697 Debris