



## Closure Checklist - Wellhead

**Closure Type:** Wellhead Closure

**Site Name:** Wardell H 18-16Jl

**Remediation #.:** 39809

**Latitude, Longitude.:** 40.219460,-104.698500

**General Condition of Site:** Good

**USCS Soil Type:** CL - Fine-grained soil - liquid limit < 50% - inorganic clays of low to med plasticity

Estimated Depth of Groundwater **more than 20' bgs**

Hydrocarbon Impacted Soils/Spills **None Observed**

Salt Crusted Soils or Impacted Vegetation **None Observed**

**Soil Samples**

#	Date	Time	Sample ID	PID	Visual	Olfactory	Equipment	Lab
1	05/15/2025	11:35 AM	WH-B01@6'	1.0	No Staining	No odor	Wellhead	
2	05/15/2025	11:38 AM	WH-B01-01@6'	1.0	No Staining	No odor	Wellhead	
3	05/15/2025	11:50 AM	WH-N01@5'	1.6	No Staining	No odor	Wellhead	
4	05/15/2025	11:52 AM	WH-E01@5'	1.4	No Staining	No odor	Wellhead	
5	05/15/2025	11:54 AM	WH-S01@5'	1.4	No Staining	No odor	Wellhead	
6	05/15/2025	11:56 AM	WH-W01@5'	1.2	No Staining	No odor	Wellhead	
7	05/15/2025	11:42 AM	WH-RIS@4'	0.6	No Staining	No odor	Flowline at Wellhead	
8	05/15/2025	11:44 AM	WH-RIS-01@4'	0.6	No Staining	No odor	Flowline at Wellhead	
9	05/15/2025	1:02 PM	WHS-N01@3"	1.1	No Staining	No odor	Wellhead Surface	
10	05/15/2025	1:04 PM	WHS-E01@3"	1.2	No Staining	No odor	Wellhead Surface	
11	05/15/2025	1:06 PM	WHS-S01@3"	0.7	No Staining	No odor	Wellhead Surface	
12	05/15/2025	1:08 PM	WHS-W01@3"	0.9	No Staining	No odor	Wellhead Surface	
13	05/15/2025	12:26 PM	WH-BG01@3'	1.0	No Staining	No odor	Wellhead Background	
14	05/15/2025	12:28 PM	WH-BG01@6'	1.1	No Staining	No odor	Wellhead Background	
15	05/15/2025	12:34 PM	WH-BG02@3'	2.0	No Staining	No odor	Wellhead Background	
16	05/15/2025	12:36 PM	WH-BG02@6'	1.9	No Staining	No odor	Wellhead Background	
17	05/15/2025	12:40 PM	WH-BG03@3'	1.7	No Staining	No odor	Wellhead Background	
18	05/15/2025	12:42 PM	WH-BG03@6'	1.5	No Staining	No odor	Wellhead Background	

19	05/15/2025	12:46 PM	WH-BG04@3'	1.3	No Staining	No odor	Wellhead Background	
20	05/15/2025	12:48 PM	WH-BG04@6'	1.6	No Staining	No odor	Wellhead Background	
21	05/15/2025	12:56 PM	WH-BG05@3'	1.5	No Staining	No odor	Wellhead Background	
22	05/15/2025	12:58 PM	WH-BG05@6'	1.4	No Staining	No odor	Wellhead Background	
23	05/15/2025	1:36 PM	FL-B01@4'	1.7	No Staining	No odor	Flowline	
24	05/15/2025	1:38 PM	FL-B02@4'	2.4	No Staining	No odor	Flowline	

1 - P1



Facing north

5 - P1



Facing south

9 - P1



Facing north

10 - P1



Facing north

11 - P1



Facing north

12 - P1



Facing north

13 - P1



Facing north

15 - P1



Facing north

17 - P1



Facing north

19 - P1



Facing north

21 - P1



Facing north

23 - P1



Facing north

24 - P1



Facing north

**Was impacted soil identified?:** No

**Total number of soil samples field screened:** 24

**Total number of soil samples collected:** 24

**Highest PID reading:** 2.4

**Total number of soil samples submitted for analysis:** 14

Was groundwater encountered during the investigation **No**

**Measured Depth to Groundwater:**

Was remedial groundwater removal conducted?

**Date groundwater  
was encountered:**

**Commencement date  
of removal:**

Sheen on groundwater?

Free product observed?

**Volume of  
groundwater  
removed prior to  
sampling:**

**Volume of  
groundwater  
removed post  
sampling:**

**Total volume of  
groundwater  
removed:**

**Total volume of  
groundwater  
samples collected:**

**Total volume of  
groundwater  
samples submitted  
to lab for analysis:**

**Signature**