

Inspection Photos

Loc: 309327

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 6/6/2025

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing west along the access road. The erosion along the road has been repaired and stabilized.



Inspection Photos



Photo 2. Facing southwest along the access road. There is rp/rap placed along the roadside where erosion was occurring.



Inspection Photos



Photo 3. Facing west along the access road. The culverts and ditches along the road have been cleaned out.



Inspection Photos



Photo 4. Facing southwest toward the wellsite. The slope was reseeded and hydromulched.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309327 | Date: 6/6/2025

Inspection Photos



Photo 5. Facing east toward the fill slope which has been seeded and hydromulched.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309327 | Date: 6/6/2025