

Inspection Photos

Location Name: RAMIREZ AC/29-72HN

Location #: 427386



Photo #1

Ramirez AC 29-72HN Battery site

Active

Equipment documented: Loc. ID 427386



Photo #2

Ramirez AC 29-72HN Battery site

Active

Wellsite(s), Battery-Facility entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: RAMIREZ AC/29-72HN
Location #: 427386



Photo #3
Ramirez AC 29-72HN Battery site
Active
Battery signage



Photo #4
Ramirez AC 29-72HN Battery site
Active
Crude oil, produced H2O tank(s): SE corner



Inspection Photos

Location Name: RAMIREZ AC/29-72HN

Location #: 427386



Photo #5

Ramirez AC 29-72HN Battery site

Active

ECD(s), Separator(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: RAMIREZ AC/29-72HN

Location #: 427386

Associated Well(s)	API	Status
<i>Primary pad^</i>		LOC # 427386
1. Ramirez AC 29-72HN	123-34975	PR

Photo #6

Ramirez AC 29-72HN Battery site

Active

Associated Well(s)

1: Producing | PR



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources