

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-27 Pad

Location ID: 312632

Date: 06/5/2025



Photo # 7792 Entrance to location






Photo # 7806 Location

Date: 06/5/2025



Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-27 Pad

Location ID: 312632

Date: 06/5/2025



Photo # 7805 Location



Photo # 7813 SW corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-27 Pad

Location ID: 312632

Date: 06/5/2025



Photo # 7814 NW corner of location



Photo # 7815 NE corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-27 Pad

Location ID: 312632

Date: 06/5/2025



Photo # 7816 SE corner of location

