

Final Reclamation and Stormwater Inspection

June 4, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 320419

Location Name: MCELWAIN #12-17

Inspection Document #: 718600651

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MCELWAIN #12-17
Location ID: 320419



Photo 1. Looking west at the mid point of the access road where it crosses a low point in the field. A portion of the access road remains. Large cobble and gravel are present.



Photo 2. Looking east across the cogis location. GPS coordinates appear to be 50 ft offset from actual location.



Inspection Photos
Location Name: MCELWAIN #12-17
Location ID: 320419



Photo 3. Looking north from wellbore according to imagery. Location appears to be within land use change involving significant earthworks. No oil and gas equipment remains.



Photo 4. Looking west from the wellbore. See photo 3 comments.

Inspection Photos
Location Name: MCELWAIN #12-17
Location ID: 320419



Photo 3. Looking south from the wellbore. See photo 3 comments.



Photo 4. Looking east from the wellbore. See photo 3 comments.



Inspection Photos
Location Name: MCELWAIN #12-17
Location ID: 320419




Photo 5. Google earth aerial photo taken 06/2017. Access road and well location are in cropland. GPS data of wellbore location appears to be approximately 50 ft off from imagery.

Inspection Photos
Location Name: MCELWAIN #12-17
Location ID: 320419




Photo 6. Google earth aerial photo taken 03/2025. Location appears to be located in land use change with significant earthworks conducted. Access road is present in cropland.