

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, STRANAHAN-66S92W/27NWNE

Location ID: 335437

Date: 6/5/2025



Location Overview – Photo #09162



Location – Photo #09163

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, STRANAHAN-66S92W/27NWNE

Location ID: 335437

Date: 6/5/2025



Location – Photo #09167



Location – Photo #09172



Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, STRANAHAN-66S92W/27NWNE

Location ID: 335437

Date: 6/5/2025



Location – Photo #09181



Illegible Wellhead Sign – Photo #09164

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, STRANAHAN-66S92W/27NWNE

Location ID: 335437

Date: 6/5/2025



Illegible Wellhead Sign – Photo #09165



Illegible Wellhead Sign – Photo #09166



Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, STRANAHAN-66S92W/27NWNE

Location ID: 335437

Date: 6/5/2025



BMP Failure/Transport of Sediment Offsite – Photo #09169



BMP Failure/Transport of Sediment Offsite – Photo #09170

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, STRANAHAN-66S92W/27NWNE

Location ID: 335437

Date: 6/5/2025



Stored Supplies – Photo #09180