

Inspection Photos
Location Name: Wells Ranch USX AE 31-09P
Location ID: 302394



Photo 1 – Wellhead



Photo 2 – OOSLAT Tag not visible

Inspection Photos
Location Name: Wells Ranch USX AE 31-09P
Location ID: 302394



Photo 3 – Tank Battery - Tumbleweed