

**Inspection Photos**  
**Location Name: Wells Ranch USX AE 21-12C**  
**Location ID: 310627**



**Photo 1 – Well Site – Pumping Unit has been removed**



**Photo 2 – Automation Equipment**

**Inspection Photos**  
**Location Name: Wells Ranch USX AE 21-12C**  
**Location ID: 310627**



**Photo 3 – Unused Engine Exhaust, Day Tank & Secondary Containment and PVC Pipe**



**Photo 4 – Wellhead – Unmarked Riser**



## Inspection Photos

Location Name: Wells Ranch USX AE 21-12C

Location ID: 310627



**Photo 5 – Wellhead**