

## Inspection Photos

Location Name: WELLS RANCH USX AA-66N63W/15NENW

Location #: 302503



Photo #1

Wells Ranch USX AA 15-03 (123-29246) Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: Balanced plug



Photo #2

Wells Ranch USX AA 15-03 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: Balanced plug

Site safety signage



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: WELLS RANCH USX AA-66N63W/15NENW

Location #: 302503



**Photo #3**

**Wells Ranch USX AA 15-03** Wellsite

**Plugged & Abandoned | PA**

**Plugging Ops; Cementing: Balanced plug**

*Wellsite entrance 1*



**Photo #4**

**Wells Ranch USX AA 15-03** Wellsite

**Plugged & Abandoned | PA**

**Plugging Ops; Cementing: Balanced plug**

*Wellsite entrance 2*




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

# Inspection Photos

Location Name: WELLS RANCH USX AA-66N63W/15NENW  
Location #: 302503



**Photo #5**  
**Wells Ranch USX AA 15-03 Wellsite**  
**Plugged & Abandoned | PA**  
**Plugging Ops; Cementing: Balanced plug**  
*JSA: 2025-06-09*

