

Inspection Photos
Location Name: Simpson 26 Pad
Location ID: 457767



Production facility




Wellhead sign

Inspection Photos
Location Name: Simpson 26 Pad
Location ID: 457767



West berm



West berm

Inspection Photos
Location Name: Simpson 26 Pad
Location ID: 457767



East berm



Stained soil

Inspection Photos
Location Name: Simpson 26 Pad
Location ID: 457767



Energy & Carbon Management Commission
40.63253, -104.73521, 1513.0m, 262°
05/11/2025 11:30:44

Stained soil



Energy & Carbon Management Commission
40.63253, -104.73534, 1512.9m, 89°
05/11/2025 1:29:56

Stained soil