

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BMC B PAD

Location ID: 447695

Date: 6/10/2025



Jun 10, 2025 at 12:53:34
Parachute CO 81635
United States

Location Overview – Photo #09226



Jun 10, 2025 at 13:00:39
Parachute CO 81635
United States

Location – Photo #09235

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BMC B PAD

Location ID: 447695

Date: 6/10/2025



Location – Photo #09227



Location – Photo #09233

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BMC B PAD

Location ID: 447695

Date: 6/10/2025



Jun 10, 2025 at 12:57:54
Parachute CO 81635
United States

Location – Photo #09231



Jun 10, 2025 at 12:58:06
Parachute CO 81635
United States

Location – Photo #09232

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BMC B PAD

Location ID: 447695

Date: 6/10/2025



Location – Photo #09236



Wildlife Entry Hazard – Photo #09228

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BMC B PAD

Location ID: 447695

Date: 6/10/2025



PRV Terminates in Unsafe Manner – Photo #09234

