

Inspection Photos

Operator: **ROBERT L BAYLESS PRODUCER LLC - 6720**

Location Name: **WEAVER RIDGE #27-16**

Location ID: **311844** API #: **05-103-10578**

Inspection Date: **6/11/2025** Inspection Doc#: **693808826**



Location overview looking W



Injection wellhead

Inspection Photos

Operator: **ROBERT L BAYLESS PRODUCER LLC - 6720**

Location Name: **WEAVER RIDGE #27-16**

Location ID: **311844** API #: **05-103-10578**

Inspection Date: **6/11/2025** Inspection Doc#: **693808826**



Used filters socks outside pump housing



Tank Battery

Inspection Photos

Operator: **ROBERT L BAYLESS PRODUCER LLC - 6720**

Location Name: **WEAVER RIDGE #27-16**

Location ID: **311844** API #: **05-103-10578**

Inspection Date: **6/11/2025** Inspection Doc#: **693808826**



Tank Battery for producing well



Pump Jack on producing well

Inspection Photos

Operator: **ROBERT L BAYLESS PRODUCER LLC - 6720**

Location Name: **WEAVER RIDGE #27-16**

Location ID: **311844** API #: **05-103-10578**

Inspection Date: **6/11/2025** Inspection Doc#: **693808826**



Combustor



Separator and Meter Housing