

Inspection Photos
Location: McCormick 24-3 #6
Location ID: 321579
API # 05-017-06275



Photo 1 –Well placard



Photo 2 – Wellhead

Inspection Photos
Location: McCormick 24-3 #6
Location ID: 321579
API # 05-017-06275



Photo 3 – Excavation area



Photo 4 – Groundwater in excavation

Inspection Photos
Location: McCormick 24-3 #6
Location ID: 321579
API # 05-017-06275



Photo 5 – Excavation



Photo 6 – 5 gallon buckets with no containment