

Inspection Photos  
Location Name: Fonte 11-22  
API Number: 125-07581



1. Lease sign at well location.



2. View of wellhead.

**Inspection Photos**  
**Location Name: Fonte 11-22**  
**API Number: 125-07581**



**3. Gas Meter inside Meter Shed.**



**4. View of damaged stock panel.**





**Inspection Photos**  
**Location Name: Fonte 11-22**  
**API Number: 125-07581**



**5. View of damaged stock panel.**



**6. Well location overview.**