

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: MILLER-62N67W 17SESE

Loc ID: 319620

Inspection: 717100205



Exhibit A

CA: An unmarked soil stockpile was observed on location with no/inadequate stormwater BMPs. No liner was visible. Operator shall comply with Rule 913.b.(5).B.iv. and properly store, handle, and manage all E&P Waste to prevent contamination of stormwater, surface water, Groundwater, and soil.

CA Resolution: Operator has used some road base to smooth out the pad and removed the dirt pile in order to comply with Rule 913.b.(5).B.iv.