

# Inspection Photos

May 27th, 2025

Operator: PDC/Chevron

Location ID: 323474

Inspection Document #: 714002206

Weld County, CO

Township: SWSE 19 5N 64W 6

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Phil Wilson 19-1

Location ID: 323474

May 27, 2025  
259° W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 1.** View of the project area taken from the eastern edge facing center.

API #: 123-13084

Inspection Photos

Location Name: Phil Wilson 19-1

Location ID: 323474



May 27, 2025  
69° E



**Photo 3.** View of adjacent reference area taken from the western edge facing east.