

Inspection Photos

Location Name: WELLS RANCH USX AA-66N63W/13SESE

Location #: 302543



Photo #1

Wells Ranch USX AA 13-16 (123-29305) Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: Cement-surface




Photo #2

Wells Ranch USX AA 13-16 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: Cement-surface

Site safety signage

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: WELLS RANCH USX AA-66N63W/13SESE

Location #: 302543



Photo #3

Wells Ranch USX AA 13-16 Wellsite
 Plugged & Abandoned | PA
 Plugging Ops; Cementing: Cement-surface
 Wellsite entrance
 prior photo




Photo #4

Wells Ranch USX AA 13-16 Wellsite
 Plugged & Abandoned | PA
 Plugging Ops; Cementing: Cement-surface
 JSA: 2025-06-13



COLORADO

Energy & Carbon Management
 Commission

Department of Natural Resources