

Inspection Photos

API: 009-06567

Operator: WEST TEXAS OPERATING
CO LLC DBA XTREME ENERGYCO

Inspection Date: 6/16/2025

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north toward the offsite tank battery. The tank berm has been rebuilt for sufficient secondary containment.



Inspection Photos



Photo 2. The netting on the tank has been repaired and maintained. There is a leak that occurred which was contained in the secondary containment.



Inspection Photos



Photo 2. There is a leak at the tank which needs to be repaired. New tank may be needed.

