

# Inspection Photos

API: 009-06574

Operator: WEST TEXAS OPERATING  
CO LLC DBA XTREME ENERGYCO

Inspection Date: 6/16/2025

County: BACA



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast toward the offsite tank battery. The tank berm has been rebuilt for sufficient secondary containment.



## Inspection Photos



**Photo 2.** The netting on the tank has been repaired and maintained.



## Inspection Photos



**Photo 3.** The sign has been reinstalled. There are weeds around the equipment that need to be controlled.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:009-06574 | Date: 6/16/2025