

Inspection Photos

API: 009-06577

Operator: WEST TEXAS OPERATING
CO LLC DBA XTREME ENERGYCO

Inspection Date: 6/16/2025

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north toward the offsite tank battery. The tank berm has been rebuilt for sufficient secondary containment. The netting on the tank has been repaired and maintained. Sign and labels appear to be updated. There are weeds around the equipment that need to be controlled.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06577 | Date: 6/16/2025