

Final Reclamation and Stormwater Inspection

Date: 06/11/2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120

Location ID: 302901

Inspection Document #: 718700474

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pavistma 4-22
Location ID: 302901



Photos 1 & 2. Taken along the access road, facing west (Photo 1; left) and east (Photo 2; right). Road base material remains throughout and will need to be removed.

Inspection Photos
Location Name: Pavistma 4-22
Location ID: 302901



Photos 3 & 4. Taken along the former access road, south of the well location. Photo illustrates the presence of a CO List B Noxious Weed (Musk Thistle) that will need to be managed for.

Inspection Photos
Location Name: Pavistma 4-22
Location ID: 302901



Photos 5 & 6. Taken from the well location facing north (Photo 5; left) and east (Photo 6; right). The well location appears to be progressing towards reclamation standards with vegetation reflective of the reference areas. Operator shall continue to monitor and manage the location for stormwater and undesirable vegetation until the location meets Rule 1004 standards and regulations.

Inspection Photos
Location Name: Pavistma 4-22
Location ID: 302901



Photos 7 & 8. Taken from the well location facing south (Photo 7; left) and west (Photo 8; right). See comments in Photos 5 & 6 for additional information.

Inspection Photos
Location Name: Pavistma 4-22
Location ID: 302901



Photos 9 & 10. Groundwater monitoring wells remain around the former well location and will need to be removed.



Inspection Number: 718700474

Inspection Photos
Location Name: Pavistma 4-22
Location ID: 302901



Photo 11. Continued from Photos 9 & 10. Groundwater monitoring wells remain around the former well location and will need to be removed.