

# Inspection Photos

API: 009-06271

Operator: ENERGY ALLIANCE COMPANY

Inspection Date: 6/16/2025

County: BACA



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Drone aerial photo facing west toward the former wellsite. There is no crop growth at the ~100'x70' bare area.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:009-06271 | Date: 6/16/2025

## Inspection Photos



**Photo 2.** Drone aerial photo facing east toward the former wellsite. There is no crop growth at the ~100'x70' bare area.



## Inspection Photos



**Photo 3.** Facing west toward the surrounding uniform crop cover.

