

Inspection Photos

Location Name: JASMINE AC/21-16

Location #: 415625



Photo #1

Jasmine AC 21-16 (123-31186) Wellsite

Producing | PR



Photo #2

Jasmine AC 21-16 Battery site

Active

Equipment documented: Loc. ID 415625



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: JASMINE AC/21-16
Location #: 415625



Photo #3
Jasmine AC 21-16 Battery site
Active
Wellsite(s), Battery entrance

