

TEP
MDP 15
Location ID: 417787



Location



Location

TEP
MDP 15
Location ID: 417787



Location



Staining under valves

TEP
MDP 15
Location ID: 417787




Staining under valves



Tank labels weathered

TEP
MDP 15
Location ID: 417787



Well signs not maintained



Well signs not maintained

TEP
MDP 15
Location ID: 417787



Debris

TEP
MDP 15
Location ID: 417787

