

# Inspection Photos

June 17th, 2025

Operator: San Marco Petroleum

Location ID: 325494

Inspection Document #: 714002232

La Plata County, CO

Township: NESW 2 33N 13W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: West Alkali Gulch 1  
Location ID: 325494

June 17, 2025  
228° SW





# Inspection Photos

Location Name: West Alkali Gulch 1

Location ID: 325494



**Photo 2.** Cardinal photos taken from the center of the project area.  
Left photo facing north, right photo facing east.



Inspection Photos  
Location Name: West Alkali Gulch 1  
Location ID: 325494



**Photo 3.** Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west.



Inspection Photos  
Location Name: West Alkali Gulch 1  
Location ID: 325494

June 17, 2025  
126° SE



**Photo 4.** View of access road which has not been reclaimed per 1004 rules.