

Inspection Photos

June 17th, 2025

Operator: San Marco Petroleum

Location ID: 385591

Inspection Document #: 714002233

La Plata County, CO

Township: SESW 32 34N 12W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

June 17, 2025
107° E



Photo 1. View of the project area taken from the western edge facing center.

Inspection Photos
Location Name: Parker 1
Location ID: 325494



Photo 2. Cardinal photos taken from the center of the project area. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Parker 1
Location ID: 325494



Photo 3. Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west.

June 17, 2025
158° S



Photo 4. Large patch of Cheatgrass dominating project area.

June 17, 2025
299° NW



Photo 5. View of reference area composed of Yucca, Juniper, Indian Ricegrass and Squirrel Tail.