

Inspection Photos

06/18/2025

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324421

Inspection Doc: 718100605

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324421



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east. Photos show final reclamation work including recontouring/regrading, replacement of topsoil and reseeding has been performed. Reclamation status is “in process”.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324421



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324421



Photo 3: Photo example showing vegetation on Location; cheatgrass is prevalent throughout the site, tough desirable plant species appears to be out-competing the weed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324421



Photo 4: Photo shows access road leading to the site has also been reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources