

# Inspection Photos

06/18/2025

**Operator:** LARAMIE ENERGY LLC - 10433

**Location ID:** 324292

**Inspection Doc:** 718100607

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 324292



**Photo 1:** 2006 Google Earth aerial image of the Location. Photo shows Location during what appears to be drilling operations of the well.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 324292



**Photo 2:** Most current (5/2025) google earth aerial imagery. Photo shows that the Location remains unchanged since site construction and drilling operations. Interim reclamation pursuant to 1003 requirements has not been performed. Red polygon represents approximate areas of the Location not necessary for production.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 324292



**Photo 3:** See comments under photo 2.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 324292



**Photo 4:** Photos 1-2 taken from the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south. Photos examples showing interim reclamation pursuant to 1003 requirements has not been performed on the Location. Additionally, Reclamation Specialist was unable to locate any topsoil stored on the Location for future reclamation efforts.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 324292



**Photo 5:** See comments under photo 4.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 324292



**Photo 6:** Photos 6-7 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east. See comments under photo 4.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 324292



**Photo 7:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 324292



**Photo 8:** Photo shows well on Location. Cellar at the well has not been covered or backfilled.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 324292



**Photo 9:** Continued from photo 8. Photo shows cellar has neither been backfilled, or properly covered. Cellar has filled with fluids. Wildlife mortality observed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources