

Inspection Photos

06/18/2025

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335647

Inspection Doc: 718100619

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335647



Photo 1: Photos taken from the west end of the Location. Photos provide an overview of the Location from northeast to southeast.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335647



Photo 2: Photo shows wells on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335647



Photo 3: Photo shows open pipes observed on the north end of the Location. Pipes have not been properly capped/covered and are accessible by wildlife.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335647



Photo 4: Signage at Location entrance. Permit information not conspicuously posted on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources