

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404078643
Receive Date:
02/03/2025

Report taken by:
Chris Sanchez

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECOM is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>NOBLE ENERGY INC</u>	Operator No: <u>100322</u>	Phone Numbers
Address: <u>1099 18TH STREET SUITE 1500</u>		
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Dan Peterson</u>	Email: <u>danpeterson@chevron.com</u>	Phone: <u>(970) 730-7281</u>
		Mobile: <u>()</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 26899 Initial Form 27 Document #: 403292062

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

Yes Multiple Facilities

Facility Type: <u>WELL</u>	Facility ID: _____	API #: <u>123-24129</u>	County Name: <u>WELD</u>
Facility Name: <u>Sater USX CC 19-23</u>	Latitude: <u>40.294100</u>	Longitude: <u>-104.475800</u>	
	** correct Lat/Long if needed: Latitude: <u>40.294090</u>	Longitude: _____	
QtrQtr: <u>NWSE</u>	Sec: <u>19</u>	Twp: <u>4N</u>	Range: <u>63W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>
Facility Type: <u>LOCATION</u>	Facility ID: <u>306177</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>SATER USX CC-64N63W 19NWSE</u>	Latitude: <u>40.294100</u>	Longitude: <u>-104.475800</u>	
	** correct Lat/Long if needed: Latitude: _____	Longitude: _____	
QtrQtr: <u>NWSE</u>	Sec: <u>19</u>	Twp: <u>4N</u>	Range: <u>63W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SW _____

Most Sensitive Adjacent Land Use Rangeland _____

Is domestic water well within 1/4 mile? No _____

Is surface water within 1/4 mile? No _____

Is groundwater less than 20 feet below ground surface? No _____

Other Potential Receptors within 1/4 mile

Within Pronghorn Winter Concentration Area

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input checked="" type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input checked="" type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	NA	Lab analysis and field screening if encountered
No	SOILS	Refer to ECMC Document #403924088	Lab analysis and field screening

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Pursuant to ECMC Rule 911 a site investigation was conducted pertaining to the SATER USX CC19-23 wellhead cut and cap and flowline removal. Approximately 101' of flowline was removed. The wellhead was cut and capped per ECMC rules.

Tank battery decommissioning was conducted pursuant to ECMC Rule 911 at the SATER CC 19-9,10,15,16,23 Tank Battery location.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

A grab soil sample was collected at the base of the excavation or the area showing the highest degree of impact during field screening activities at the wellhead excavation. A grab confirmation soil sample was collected at the wellhead excavation. Grab confirmation soil samples were collected from the produced water vessel(s) excavation, beneath the ground oil tank(s), and at the risers for the flowline(s) and dumpline(s) of any separator(s). Soil samples were analyzed by a certified laboratory for TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons), organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, and boron. All samples collected were analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

If groundwater is encountered during the site investigation, grab groundwater samples will be collected and analyzed for all organic and inorganic compounds per ECMC Table 915-1.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Visual inspection of the wellhead, flowline, and tank battery areas occurred during abandonment activities. Field personnel field screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling was required. A detailed summary of decommissioning activities, including field notes, site photos, figures, and laboratory analytical results, is attached to ECMC Document Nos. 403498915 & 403673040.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

NA / ND

Number of soil samples collected 10

ND Highest concentration of TPH (mg/kg) _____

Number of soil samples exceeding 915-1 2

-- Highest concentration of SAR 1.46

Was the areal and vertical extent of soil contamination delineated? Yes

BTEX > 915-1 No

Approximate areal extent (square feet) 200

Vertical Extent > 915-1 (in feet) 6

Groundwater

Number of groundwater samples collected 0

Highest concentration of Benzene (µg/l) _____

Was extent of groundwater contaminated delineated? Yes

Highest concentration of Toluene (µg/l) _____

Depth to groundwater (below ground surface, in feet) _____

Highest concentration of Ethylbenzene (µg/l) _____

Number of groundwater monitoring wells installed _____

Highest concentration of Xylene (µg/l) _____

Number of groundwater samples exceeding 915-1 _____

Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected

 Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

One background soil sample was collected by Eagle Environmental Consulting, LLC. during wellhead decommissioning. Due to the proximity to the facility pad, this background sample will not be used as a comparison to native soil conditions on site.

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____

Volume of liquid waste (barrels) _____

Is further site investigation required?

A supplemental site investigation (SSI) will be completed to confirm Table 915-1 compliance at soil sample locations WH-FS-01@6', FS01@6', SS01@2.5', AST01@0.5', AST02@0.5', SEP01-DL@3', SEP01-FL@4.5', SEP02-DL@3', SEP02-FL@4.5', SEP03-FL@4.5'. Additionally, background samples (BKG01-BKG05) will be collected to assess native soil conditions at the site. Soil samples will be analyzed for metals in soil per ECMC Table 915-1, pH, SAR, EC, and boron. Should analytes remain in exceedance of ECMC Table 915-1 standards and background levels, an additional SSI will be proposed to delineate the remaining exceedances.

The SSI is tentatively scheduled to take place on May 20, 2025 and the results of which will be submitted on a subsequent Form 27.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

No impacted material caused by oil and gas operations was identified at this time

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

A supplemental site investigation (SSI) will be completed to confirm Table 915-1 compliance at soil sample locations WH-FS-01@6', FS01@6', SS01@2.5', AST01@0.5', AST02@0.5', SEP01-DL@3', SEP01-FL@4.5', SEP02-DL@3', SEP02-FL@4.5', SEP03-FL@4.5'. Additionally, background samples (BKG01-BKG05) will be collected to assess native soil conditions at the site. Soil samples will be analyzed for metals in soil per ECMC Table 915-1, pH, SAR, EC, and boron. Should analytes remain in exceedance of ECMC Table 915-1 standards and background levels, an additional SSI will be proposed to delineate the remaining exceedances.

The SSI is tentatively scheduled to take place on May 20, 2025 and the results of which will be submitted on a subsequent Form 27.

Soil Remediation Summary

In Situ

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

Ex Situ

- _____ Excavate and offsite disposal
- _____ If Yes: Estimated Volume (Cubic Yards) _____
- _____ Name of Licensed Disposal Facility or ECMC Facility ID # _____
- _____ Excavate and onsite remediation
- _____ Land Treatment
- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Other _____

Groundwater Remediation Summary

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered during decommissioning activities.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other First Quarter 2025 - Timeline Update

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policy MWZZ 316714) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? Yes _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 03/31/2023

Proposed date of completion of Reclamation. 02/27/2026

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 12/08/2022

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 03/31/2023

Proposed site investigation commencement. 05/20/2025

Proposed completion of site investigation. 05/27/2025

REMEDIAL ACTION DATES

Proposed start date of Remediation. 05/27/2025

Proposed date of completion of Remediation. 08/27/2025

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The implementation schedule has been changed due to the necessity for supplemental site investigation (SSI) activities adjacent to the former wellhead and tank battery. A SSI will be completed to confirm Table 915-1 compliance at soil sample locations WH-FS-01@6', FS01@6', SS01@2.5', AST01@0.5', AST02@0.5', SEP01-DL@3', SEP01-FL@4.5', SEP02-DL@3', SEP02-FL@4.5', SEP03-FL@4.5'. Additionally, background samples (BKG01-BKG05) will be collected to assess native soil conditions at the site. Soil samples will be analyzed for metals in soil per ECMC Table 915-1, pH, SAR, EC, and boron. Should analytes remain in exceedance of ECMC Table 915-1 standards and background levels, an additional SSI will be proposed to delineate the remaining exceedances.

The SSI is tentatively scheduled to take place on May 20, 2025 and the results of which will be submitted on a subsequent Form 27.

OPERATOR COMMENT

This Supplemental Form 27 is being submitted as a first quarter 2025 timeline update for the former Sater USX CC-64N63W 19NWSE wellhead and tank battery location.

A supplemental site investigation (SSI) will be completed to confirm Table 915-1 compliance at soil sample locations WH-FS-01@6', FS01@6', SS01@2.5', AST01@0.5', AST02@0.5', SEP01-DL@3', SEP01-FL@4.5', SEP02-DL@3', SEP02-FL@4.5', SEP03-FL@4.5'. Additionally, background samples (BKG01-BKG05) will be collected to assess native soil conditions at the site. Soil samples will be analyzed for metals in soil per ECMC Table 915-1, pH, SAR, EC, and boron. Should analytes remain in exceedance of ECMC Table 915-1 standards and background levels, an additional SSI will be proposed to delineate the remaining exceedances.

The SSI is tentatively scheduled to take place on May 20, 2025 and the results of which will be submitted on a subsequent Form 27.

As noted in ECMC Document No. 404029645, this form is being submitted to reset the 90-day reporting period and evenly distribute the reporting requirement across the entire quarter.

Quarterly recording will be conducted until closure criteria are met for this remediation project.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Mike Medina

Title: Environmental Consultant

Submit Date: 02/03/2025

Email: tas-chevron-2@tasman-geo.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Chris Sanchez

Date: 06/25/2025

Remediation Project Number: 26899

COA Type

Description

	ECMC has processed this form as an update; no analytical was attached thus approval of this form does not imply any agreement with comments on completion of site investigation. All ongoing/unaddressed comments/COAs from previous Forms remain applicable.
1 COA	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

404078643	FORM 27-SUPPLEMENTAL-SUBMITTED
404078784	SITE INVESTIGATION PLAN

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)