



RAT Observation

- No Observed Source Material (3)
- Possible Source Material (0)
- Source Material Observed (0)



T060 RES - SCHROTH JON - 35740 CR 49 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Observation

Oiling Observation: 0 No Observable Oil | Id: 554813 | 5/22/2025 3:55:01 PM
(40.518416, -104.600745)
Garage doors on residence West side



Oiling Observation: 0 No Observable Oil | Id: 554814 | 5/22/2025 4:26:08 PM
(40.518411, -104.600692)

Horse Trailer on north end of property





T060 RES - SCHROTH JON - 35740 CR 49 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 554816 | 5/22/2025 4:29:06 PM
(40.518374, -104.601201)
Secondary residence on West side of property facing well

