

# Final Reclamation Inspection

May 15, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 310546

Inspection Document #: 718800354

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BUTTERBALL #B4-19  
Location ID: 310546



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that the well location meets Rule 1004 standards. A pipeline was installed following plugging and abandonment of the well location, and all disturbances are contained within this pipeline development.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: BUTTERBALL #B4-19  
Location ID: 310546



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: BUTTERBALL #B4-19  
Location ID: 310546



**Photo 5.** Photo taken from the access road, facing North towards the well location. Photo illustrates that disturbances along the access road are contained within a pipeline development following plugging of the well.



**Photo 6.** Photo taken of the reference area, east of the location, facing North. Photo illustrates perennial grass vegetation.

