

Inspection Photos

Location Name: CECIL USX A-66N64W/1NWSE

Location #: 332935



Photo #1

Cecil USX A 1-10 (123-24341) Wellsite

Temporarily Abandoned | TA

Emergency number: Peeling

Housekeeping: Weed control



Photo #2

Cecil USX A 1-10, 1-7, 01-08, 01-09 Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Cecil USX A 01-11D, 01-01, 01-02, 01-03, 01-04,

01-05 D, 1-6, 1-17, 1-19

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: CECIL USX A-66N64W/1NWSE

Location #: 332935



Photo #3

Cecil USX A 1-10, 1-7, 01-08, 01-09 Battery site

Abandoned: ALL Equipment Removed

Well(s) entrance



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources