

# Inspection Photos

05/30/2025

Operator: QB ENERGY OPERATING LLC

#10844

Location ID: 334922

Inspection Doc: 719200028

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334922



**Photo 1:** Photos taken from the east end of the Location provide an overview to the west and north, respectively. Vegetation is composed of smooth brome, western wheatgrass and intermediate wheatgrass. Vegetation appears to meet 1004 final reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334922



**Photo 2:** Photo taken from the central portion of the Location provides an overview looking south. Vegetation appears to meet 1004 final reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334922



**Photo 3:** A steel cable protruding from the ground on the western portion of the Location. Removal is advised.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334922



**Photo 4:** Photo showing the adjacent reference area to the south of the Location is used for livestock grazing and is mostly composed of big sagebrush and native grasses.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources