


| Site Information | |
|------------------|--------------------|
| Site Name | Palomares 23-4L WH |
| Date | 2/19/2015 |
| Sampler | Kendra Corcos |
| Weather | 10° sunny |

| Gas Meter Information | |
|-----------------------|-----------|
| Make/Model | Geom 5000 |
| S/N | 5077 |

| Calibration Information | |
|--|------|
| Gas | Time |
| Pure N ₂ | 1322 |
| Fresh Air | 1320 |
| 50 ppm CO, 10 ppm H ₂ S | 1324 |
| 15% CH ₄ , 15% CO ₂ , Bal N ₂ | 1326 |



| Bump Test | | | | | | |
|-----------|-----------------|---------------------|---------------------|--------------------|------------------------|----------|
| Time | | CH ₄ (%) | CO ₂ (%) | O ₂ (%) | H ₂ S (ppm) | CO (ppm) |
| 1335 | Calibration Gas | 15.0 | 15.0 | 0.0 | 0 | 0 |
| | Readings | 14.8 | 14.9 | 0.0 | 0 | 0 |

| Field Readings | | | | | | | | | | |
|----------------|------|---------------------|---------------------|--------------------|------------------------|----------|--------------|----------------|-----------|----------|
| Point ID | Time | CH ₄ (%) | CO ₂ (%) | O ₂ (%) | H ₂ S (ppm) | CO (ppm) | Purge Length | Sampled? (Y/N) | Sample ID | Comments |
| SV01 | 1337 | 0.0 | 1.6 | 20.9 | 0 | 0 | 65 | N | | Blocked |
| SV02 | | | | | | | | | | |
| SV03 | 1339 | 0.0 | 1.1 | 21.1 | 0 | 0 | 63 | N | | |
| SV04 | 1341 | 0.0 | 0.3 | 21.3 | 0 | 0 | 66 | N | | |
| SV05 | 1343 | 0.0 | 0.3 | 21.4 | 0 | 1 | 67 | N | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Notes and Observations