

# SVE Trailer Inspection

Workflow : 19407

## Inspection Information

Responsible Person ID	Romana Cowden (ID: 7943)
TrueContext Username	tdobransky@entradainc.com
Name of Inspector	Chance Holder
Equipment	Solar SVE Trailer #2 (Trailer, ID: 472162)
Date	2025-04-25
Lat/Long	39.6072589952101, -108.143526013303
Hours Run	12056.3
PID	3723
Liquid in Knockout	Yes
Notes	DZSA Lateral- 3/4 OT KNOCKOUT full of liquid