

SVE Trailer Inspection

Workflow : 19667

Inspection Information

Responsible Person ID	Romana Cowden (ID: 7943)
TrueContext Username	tdobransky@entradainc.com
Name of Inspector	Chance Holder
Equipment	Solar SVE Trailer #2 (Trailer, ID: 472162)
Date	2025-05-09
Lat/Long	39.6072765160645, -108.143579559209
Hours Run	12089.9
PID	3986
Liquid in Knockout	Yes
Notes	D23A Lateral- 250ml of fluid