

SVE Trailer Inspection

Workflow : 20192

Inspection Information

Responsible Person ID	Romana Cowden (ID: 7943)
TrueContext Username	tdobransky@entradainc.com
Name of Inspector	Chance Holder
Equipment	Solar SVE Trailer #2 (Trailer, ID: 472162)
Date	2025-06-05
Lat/Long	39.6072371397536, -108.143584197488
Hours Run	12208.2
Liquid in Knockout	Yes
Notes	D23A Lateral- Barely any liquid