

SVE Trailer Inspection

Inspection Information

Responsible Person ID	Romana Cowden (ID: 7943)
TrueContext Username	brollins@caerusoilandgas.com
Name of Inspector	Blair Rollins
Equipment	Solar SVE Trailer #2 (Trailer, ID: 472162)
Date	2025-04-07
Lat/Long	39.6071578773935,-108.143561279674
Hours Run	11975
PID	2060
Liquid in Knockout	Yes
Notes	D23A
Photos	See workflow attachments.

File Attachments

Image

