

Inspection Photos

API: 071-08471

Operator: OGRIS OPERATING LLC

Inspection Date: 6/30/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west at the beginning of the reclaimed access road. Vegetation is beginning to emerge.



Inspection Photos



Photo 2. Drone aerial photo facing west toward the reclaimed access road..



Inspection Photos



Photo 3. Facing southwest toward the reclaimed location.



Inspection Photos



Photo 4. Drone aerial photo facing southeast.



Inspection Photos



Photo 5. Drone aerial photo facing east toward the reclaimed location and access road.

