

Inspection Photos

API: 071-06343

Operator: OGRIS OPERATING LLC

Inspection Date: 6/30/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward the location. The electric utility line has been removed back to towards the active well to the east.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06343 | Date: 6/30/2025

Inspection Photos



Photo 2. Facing west at the abandoned wellsite. This area of the former road needs to be reseeded. There is mostly weeds (Kochia) growing in the area between the two blue lines.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06343 | Date: 6/30/2025

Inspection Photos



Photo 4. Facing north at the location. The electric line has been removed but some of the powerpoles still remain.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06343 | Date: 6/30/2025