

# Inspection Photos

API: 071-07415

Operator: OGRIS OPERATING LLC

Inspection Date: 6/30/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast toward the location. The perennial vegetation has established to reference area levels.





## Inspection Photos



**Photo 2.** Facing southeast at the location. The perennial vegetation has established to reference area levels..





## Inspection Photos



**Photo 3.** Facing southeast at the location. The perennial vegetation has established to reference area levels..





## Inspection Photos



**Photo 4.** Facing west at the location. The perennial vegetation has established to reference area levels.

