

Inspection Photos

API: 071-06191

Operator: OGRIS OPERATING LLC

Inspection Date: 6/30/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the wellsite.



Inspection Photos



Photo 2. The grate does not fully cover the well cellar.



Inspection Photos



Photo 3. Well sign is posted at meter shed..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-06191 | Date: 6/30/2025